

Check List for - Title: D&D Facility Characterization - Interviews

## D&D Facility Characterization Interview Checklist

ID No.: <u>\$770 SHED</u> Date: <u>10/09/00</u>

Page 1 of 2

CRITERIA:	Λ D&D Characterization Protocol, RFETS MAN-077-DDCP, Rev. 0
	Λ Facility Disposition Program Manual, RFETS MAN-076-FDPM
	Λ RFETS Radiological Safety Practices, January 12, 1998
Facility Name & Type (1, 2, or 3) S770 SHED, Type 1 Facility, Carpenter Storage Shed	
Personnel Interviewed (Name & Title/Function) Don L. Cox, Mechanical Engineer V, D&D Closure	
	Y/N
Does a current WSRIC exist for the facility?	
If so, are there exceptions to the WSRIC as written?	
COMMENTS (incl. WSRIC contacts)	
WSRIC Contact is James M. Schoen who is in charge of the WSRIC Reports, T130J, X3579, C-83.	
Are rad surveys available that indicate current status of the facility? N	
Are historical rad surveys available that indicate historical status, or evolution, of the facility?	
COMMENT N* According to Sarah J. Roberts, X3008, ARCDA, T771Q, any	
Historical data, which is probably at the Federal Center, would not be adequate for unrestricted release (i.e. Pre-	
Demolition Survey or Property Release Evaluation). New monitor surveys would have to be taken.	
Is an HRR available for the facility?N	
Do any other reports exist beyond the HRR (e.g., spill reports, reportable incidents, etc.) that further	
Characterize the facility relative to chemical &/or radiological contamination? N*	
Are engineering drawings (esp. "as-builts") available?	
* Engineering as-built drawings are not available, but facility room drawing/sketches are available.	
Are any non-conformances or issues with the facility status currently being tracked in PATS?N	
If so, what are	the issues (note in Comments, below)?
COMMENTS N	* The S770 SHED Trailer is sitting on IHSS/PAC #700-163.1 and IHSS/PAC #700-163.2
area land/soils,	as per, Nick Demos, ER Characterization/HRR Manager, X4605, Therefore, the S770 SHED
land/soils has CERCLA concerns. Engineering drawings, as-builts, do not exist for the S770 SHED	
facility, but a Facility Planning sketch does exist. The Plant quit using lead based paints for office	
buildings in 1989, if this restroom facility was painted prior to 1989, lead-based paints may have been	
used.	
Have any types of chemical characterization, incl. Asbestos, been performed recently?	
	es of characterization were performed (note in Comments, below)?
COMMENTS N	I* No ashestos characterization data exists for Trailer S770 SHFD, according to Bret

33 yz

2000 RECEIVED RECORDS CENTER

Clausen, X, Building 130, Room C-252. The asbestos data reports are located in

as backup contact for the asbestos reports.

**Print Name** 

Interviewed by: J. R. Sheets

Cubicle 273, of Building 130 and the reports are under the control of Bret Clausen with Rae Eklund

Signature

**ADMIN RECCRD** 

10/09/00

Interview Date



## **D&D Facility Characterization** Interview Checklist

ID No.: S770 SHED Date: 10/09/00

10/09/00

Interview Date

Page 2 of 2

What timeframe did the interviewee work in the facility? N/A, the facility is a wooden Carpenter Storage Shed.
Has the building configuration changed since you worked in the building? If so, in what way?
No, the facility is a wooden Carpenter Storage Shed.
What types of equipment were in the building during the interviewee's time there? None, no heat, no lights, and no equipment.  Where was the equipment located? (specific rooms/areas) NA, the facility is just a small shed without any equipment.
Were any radioactive materials or metals handled in the building? If so, what types? No, none
Which equipment handled radioactive material? <u>N/A</u>
Were any chemicals handled in the building? If so, what types? N/A
Did any spills or uncontrolled releases of radioactive materials or chemicals occur while you were working in the facility? No, none.
Were these spills/releases cleaned-up? How were they cleaned-up? N/A
Where did these spills/releases occur? N/A

Signature



Interviewed by: J. R. Sheets

Print Name